



ALTERNATE #1
EXISTING STORAGE SHED TO
BE DEMOLISHED



AREA OF
EIFS
REPAIR




AREA OF EXCAVATION
AND WATERPROOFING


ALTERNATE #2 - EIFS
REPAIR AND
WATERPROOFING





PHOTOS OF EXISTING STORAGE ROOM





PHOTOS OF EXISTING SHOWER AND LOCKER ROOM

Gray lockers to be relocated and tile floor to be removed in new ZM Office space

PHOTO OF EXISTING JANITOR CLOSET



wall cabinets to remain



wall cabinet to remain

PHOTOS OF EXISTING FOOD
PREP AND STAFF BREAK
ROOM

